





REPAIRS DUE TO WEAR AND TEAR:-

Main Engine:- H.P. cylinder lined up and ahead guide shoe - remetalled.  
H.P. eccentric straps, whole - remetalled.

Auxiliaries:- Centrifugal pump engine, piston packing rings - renewed.

Other minor repairs and adjustments effected.

NOTE:- Main Engine:- L.P. piston proper, found a small crack on its packing  
ring face, examined and found in efficient condition. K. 2



© 2020

Lloyd's Register  
Foundation

007506-007517-0187 3/2



Examinined

It is submitted that  
this vessel is eligible for  
THE RECORD, value 541

259

178/41



© 2020

Lloyd's Register  
Foundation