

S. S. TANAI.

4/1/40.

To complete this Electric Light Report new fuses to be fitted on Main Switchboard. The
ens Surveyor stated that this would be done on vessels arrival in U.K. On
ing ship yesterday the Chief Engineer stated that work would be done in Swansea
vessel sails from London today for Swansea to load.

R. P. Storey.



© 2020

Lloyd's Register
Foundation

007707 - 007713 - 0136