

17 OCT 1939

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME "NICOLE SCHIAFFINO". Rpt. Rou. No. 2076.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32)

The Rouen Surveyor reports the vessel afloat, a length of chain cable ^{found} worn below Rule limit and windlass cable lifters, port and starboard found unsatisfactory, and several upper deck plates on port side in aft well deformed and twisted.

The Surveyor recommends a length of chain cable be renewed at Owners' first convenient opportunity and that the cable lifters, port and starboard, and wasted upper deck plates on port side in aft well be renewed not later than November, 1939.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.



Handwritten signature

13.10.39

© 2020 Lloyd's Register Foundation

007714-007721-0019

Surveyor to Lloyd's Register.

ssed without f