

1

Received from Chief Surveyors

For the CHIEF SHIP SURVEYOR

Nature of Survey

When due

Repairs have been effected to damage sustained by striking pier etc.

Anchors & Chain Cables tested by American Bureau Surveyors, but the American Committee have assigned the figure 1.

100 A-1. (steel).

2 Dls (steel) & webframes. Longitudinal framing.

Cell no 328' 1069b MT 24' 666t. FRT 91b. APT 318t.

PK. 6BH *St-Cam* P38', B102', F42'.

9.12.2

15-10-20

15/10/18

The Surveyors ^{the} should be requested to state whether the record of "emi
r em" ^{the} should be made in this case

to state whether

Lloyd's Register
721-0350

007714-007721-0350

~~IN THE VI HOLY DRUG~~

~~Spacing~~ *After Peak*

7	3.4	.40	7	3.4	.40
---	-----	-----	---	-----	-----

~~Angles on ditto~~

The Plates outside Hatchways

Dark Material & thickness