

Subject to chafed bow plating port & starboard sides being dealt with at the first convenient opportunity.

Gen. 15493 (19.38) 11

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME

MAULY

Rpt.

Gen

No. 16116

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/24)

of Survey

The

Genoa

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, ~~repairs or renewals to~~  
~~and minor repairs effected.~~

The chafed bow plating, as above, continues efficient

It is submitted the vessel appears worthy to remain as  
classed with record of survey 2.40 <sup>Subject as above</sup> as recommended.

1.00 At.


2.40 Gen

Subject to.

CES

19.3.40

In SPL - Deep tank not to be used as a tank until tested.



© 2020

Lloyd's Register  
Foundation

007722 007730 0270