

DISCLOSED

RAY No. 505

(Received at London Office

MAR 21 1940

No. 16130

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 15/3/40. 19... When handed in at Local Office 15/3/40. 19... Port of GENOA.

No. in Reg. Book 22720 Survey held at GENOA. Date, First Survey & Last Survey 4/3/40. 19x
(No. of Visits One)TONNAGE: 18765 Built at Glasgow By whom W. Beardmore & Co. Ltd When 1923 4
GROSS 18765
UNDER DK. 11201 Owners LLOYD TRIESTINO
NET 11527 Managers - Owners' Address -
(if not already recorded in Appendix to Register Book)
Port belonging to TriesteSurveyed Afloat or in Dry Dock? D. Dock Name of Dock Crazie. Destined Voyage -
Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 12668, Port Tri.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., in any).
* 100 A.I. with freeboard 8-39 ss. H. Kg. N°3-11-37	* LMC. M.S. II-37 B.S. 9-39 + Lloyd's RMC. 9-39 CL. 8-39
Fitted for oil fuel 4-23 F.P. above 150°F.	
Society's Freeboard (if assigned) as painted on Ship and now verified }	

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR CONDITION-NOW DONE:- Vessel placed in dry dock. Bottom and rudder (not lifted) cleaned, examined, found in order and recoated.

Weather decks, casings and skylights, hatches, ventilators and coamings, anchors, windlass, boats, steering gear (direct coupled) and general equipment generally examined and found in order.

S.R. LIST- Indented plating examined externally and found efficient.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed	/	/	/	/	/	/	/	/
Removed and Fair or Repaired	/	/	/	/	/	/	/	/
Fair or Repaired in place	/	/	/	/	/	/	/	/

PRESENT CONDITION OF THE

Boats	Good	Bulkheads	/	Engine Room Skylights	Good	Copper, or Y.M.	/
Caulking of Decks	/	Ceiling	/	Cost Bunkers, Openings, Covers, &c.	/	(State if on Felt.)	/
Samings	/	Cement or Asphalt	/	Oil Bunkers	/	When fitted, Month	Year
Stems & Fastenings	/	Rudder	Good	Scuppers	Good	Boats	Good
Outside Plating	Good	Steering gear and its connections	/	Cargo Hatchways	/	Masts, Yards, &c.	/
" " in way of sidelights	/	Windlass	/	Hatches	/	Condition, how ascertained	Good
Stems	/	Have pumps been examined and found efficient?	not now examined	Planking	/	(State if wedges removed)	/
Reverse Frames	/	Have Sluice Valves been examined and found efficient?	/	Caulking	/	Equipment letter	1+
Longitudinals	/	Have Watertight Doors been examined and found efficient?	not now examined	Treenails	/	Anchors, No. of	38 15
Transverses	/	Have Ventilators and their Coamings been examined and found efficient?	/	Breasthooks & Stemson	/	Cables (State if now ranged)	no
Stems	/	Air and Sounding Pipes	/	Transoms, Pointers & Crutches	/	" length (on board)	mean diameter
Stringers	/	Doubling Plates under Sounding Pipes	/	Timbers of Frame at openings	/	" Rule length	stated size
Inner Bottom Plating	/		/	" " at other places	/	Chain Locker	/
Have the Tanks been examined internally?	no		/	Stringers, Clamps & Shelves	/	Hawsers & Warps	Good
Have the Tanks been tested?	M		/	Salting	/	Standing and Running Rigging	/
			/	(State if examined.)	/	Sails	/

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38"

This vessel is eligible, in my opinion, to remain as classed with fresh record of survey 3-40. This vessel's class is subject to indented plates F.8 K.11, 14, 15 (s.s.) & K.11 (ps.) being dealt with at Owners' convenience. (No Interim Certificate issued).


Survey Fee (per Section 20)	Condition Lit. 300.-	Fees applied for, 15/3/40.
Special Damage or Repair Fee (if any) (per Sec. 20)	2	Received by me, 19
Travelling Expenses (if chargeable)	32.-	
Second Surveyor's Fee (if any)	2	

Committee's Minute
Character Assigned

TUE 2 APR 1940

TUE 12 MAY 1942
CHIT CLASS
ON RE-PRINT.

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

007817-007824-0034

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]