

tot  
s.s. "DUNLUCE CASTLE"

The class is subject to sloping casing in the fore tween deck bunkers being repaired, and to indented plating on starboard side of No. 2 hold and tween decks being dealt with at the Owners' convenience.

The 3rd S.S. No. 2 became due 10.37.


In January last the vessel was generally examined by the London Surveyors, with a view to postponing the survey until the following June.

A letter has now been received from Messrs. Lambert Bros. stating that the vessel has been taken over by Messrs. Turner & Hickman Ltd., Glasgow. The vessel is at present lying in the West India Dock, London, and is leaving tomorrow night for ~~the~~ Port Glasgow where she will be broken up. The Writers desire an Interim Certificate to be issued for the voyage.

It is submitted that provided the Surveyors satisfy themselves that the vessel <sup>is machinery</sup> is in fit condition for the voyage, special attention being paid to the windlass and steering gear, an Interim Certificate could be issued as desired.

The London Surveyors should be advised accordingly.

*Bank*  
In the London Surveyors  
to note. *P.S.*



31.7.39.

© 2020  
Lloyd's Register  
Foundation  
007817-007824-0210