

DISCLOSED SECTION
REPORT OF SURVEY FOR REPAIRS, &c.
No. 117633 A
Rpt. 8. (Received at London Office.)
Date of writing Report... 19... When handed in at Local Office... 19... Port of LONDON.

No. in Survey held at... Date, First Survey... Last Survey...
Reg. Book. 06088 on the Wood, Iron or Steel. Lr Commander HOLBROOK
Built at Goole By whom Goole SB + Reg. C. H. H. When 1915
TONNAGE:— Gross 237 Owners Odefrans Ltd.
Under DK 215 Managers W. Stenhouse
Net 23 Port belonging to Hull

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Cell DBor DBa feet; uE & B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.
Last Report, No. 130427 Port Linn
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys.
Machinery and Boiler Surveys (including date of N.B., if any).
+ 100PH + LMC 3.49
Steam Trawler BS 2.00
3.49 TS 3.49 CL
SS Reg. No. 1103.11.45
In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.
Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR
If so, is the Report sent now, or when will it be sent?

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fairred or Repaired								
Fairred or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained (State if wedges removed.)
" " In way of sidelights	Have pumps been examined and found efficient?	Planking	Equipment letter
Frames	Have Stulce Valves been examined and found efficient?	Caulking	Anchors, No. of
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" length mean diam. (on board.)
Transverses	Alr and Sounding Pipes	Transoms, Poinfers & Crutches	" Rule length size
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Chain Locker
Keelsons		" " at other places	Hawsers & Warps
Stringers		Stringers, Clamps & Shelves	Standing and Running Rigging
Inner Bottom Plating		Salting	Sails
Have the Tanks been examined internally?		State if examined.	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £ : : Fees applied for, 19
Special Damage or Repair Fee (if any) £ : : Received by me, 19
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
Committee's Minute FRI 30 JUN 1950
Character Assigned Wrote John
Abn gary) Lloyd
withdraw class & insert (...)
Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 1st July 1950
Classing Committee
decision confirmed. P.E.
© 2020
007925-007833-0118