

The class is subject to the generator main cables being replaced by cables complying with the Rules at the first opportunity.

2 E

Received by Chief Engineer Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME WINSTON SPENCER CHURCHILL. REPORT Ant. No. 24908.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/42.)

Nature of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S.~~ No.

This Survey, due 5.48 ^{now} ~~partly~~ held ^{now} completed, and the following repairs carried out (due to wear and tear):-

All plain tubes and a number of stay tubes renewed.

It is submitted the vessel is eligible to remain as classed, with notation of B.S. 8.48, subject as above as recommended.



© 2021

Lloyd's Register
Foundation