

of Feed pumps *Two* Diameter of ditto *3 1/2"* Stroke *15* Can one be overhauled
 of Bilge pumps *Two*

No. an
 olds, &c.
 Is a
 essible
 hey Val
 Are th
 Ho

Copy of Original

DEVIATION CARD

or *Standard* Compass of

S. S. Manuel Rionda

Adjusted at *New York*

June 19 19 *20*

COMMANDER

Ship's Head by Compass.	DEVIATION	Ship's Head by Compass.	DEVIATION
NORTH.	<i>1° W</i>	SOUTH.	<i>1° W</i>
by E.	<i>0</i>	S. by W.	<i>0</i>
N. E.	<i>1/2° W</i>	S. S. W.	<i>1/2° W</i>
E. by N.	<i>0°</i>	S. W. by S.	<i>1/2° W</i>
E.	<i>0</i>	S. W.	<i>1/2° W</i>
E. by E.	<i>1/2° W</i>	S. W. by W.	<i>1° W</i>
N. E.	<i>0</i>	W. S. W.	<i>1° W</i>
by N.	<i>1° W</i>	W. by S.	<i>1 1/2° W</i>
EAST.	<i>0</i>	WEST.	<i>1 1/2° W</i>
by S.	<i>1° W</i>	W. by N.	<i>1 1/2° W</i>
S. E.	<i>0</i>	W. N. W.	<i>1 1/2° W</i>
E. by E.	<i>1 1/2° W</i>	N. W. by W.	<i>2° W</i>
E.	<i>0</i>	N. W.	<i>0</i>
S. E. by S.	<i>1° W</i>	N. W. by N.	<i>1 1/2° W</i>
S. S. E.	<i>0</i>	N. N. W.	<i>1 1/2° W</i>
S. by E.	<i>0</i>	N. by W.	<i>0</i>

JOHN BLISS & CO., Adjusters,

128 Front Street, New York.

Lloyd's Register
 Foundation

007938-007946-044 (over)

Water
 Thickness *1/2"* Material of Lower back plate *Steel* Thickness *1/16"* Greatest pitch
40
37

as the adjustment was made

These deviations will change
adjustment was made ~~shoo~~
after the ship was launched



© 2021

Lloyd's Register
Foundation

Deep tank, forward,

Thickness