



COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.

Port
of
Lisbon

for the examination of
the vessel named & dated at
Setubal on the 25th September 1937.

25th, September 1937.

(*Attachment: Casualty Report*)

This is to Certify that I have

surveyed the Steamer "TERNEUZEN" 2473 tons gross, whilst lying

afloat in Setubal this day. The vessel had been refloated after

being aground in the vicinity of Setubal since January last,

and that I have transmitted to the Committee of Lloyd's Register

Shipping, London, a Report, as on the other side, stating

at all repairs recommended by me have been completed to

my satisfaction, and in my opinion the vessel is fit to be

towed in ballast to Lisbon.

(Signed) A.E.Scott.


..... 220\$00

Surveyor's fee..... 150\$00

Expenses..... 5\$00

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood
that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or
certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of
judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



© 2020

Lloyd's Register
Foundation

Refused to register a vessel

REGISTRATION OFFICE

Refused to register a vessel

The decks, vent & hatch coamings, hatch covers & supports, holds, peaks & peak tanks, machinery spaces & bunkers have been examined. Windlass & steering gear tried out under working conditions & found efficient.

Double bottom tanks had been filled and were not available for examination.

(Signed) A.E.Scott.

and I will give you an account

of my examination, which was made for the purpose of determining whether the ship is fit for service.

The ship has been found to be in a fit condition for service, except that the deck fittings are not in a fit condition for service.

The ship has been found to be in a fit condition for service, except that the deck fittings are not in a fit condition for service.

The ship has been found to be in a fit condition for service, except that the deck fittings are not in a fit condition for service.

The ship has been found to be in a fit condition for service, except that the deck fittings are not in a fit condition for service.

The ship has been found to be in a fit condition for service, except that the deck fittings are not in a fit condition for service.

The ship has been found to be in a fit condition for service, except that the deck fittings are not in a fit condition for service.

and shall be liable in damages for any damage caused by the ship.

A. E. Scott (signature)

\$500.00 E...

\$150.00 E...

\$50.00 E...

\$50.00 E...

Refused to register a vessel



© 2020
Lloyd's Register
Foundation