

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space between with a plastic material insulate in a way
✓ Oil should be other appli

L. C. T. No 2.

Box. 2548
Nypc 31406
Clv. 5257

It is submitted that
this vessel is eligible for

THE RECORD. + L.M.C 6.30 CL.

Oil Engines 4 S.C.S.A 12 Cy 11"-15"

N.H.P. 142.

2 Oil Engines connected to Elec. Motor & Sc. Shaft.



© 2020

③

Lloyd's Register
Foundation

007958-007966-0029

What pipes pass through the deep tanks

... and all boiler mountings accessible at all times