

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"BULIMBA"

Rpt. Syd.

No. 20553

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.42.)

of Survey

~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH-~~

LMC due 11.43.

BS due 10.43, held on main boilers and machinery generally examined.

The donkey boiler has not been surveyed and is now blanked off.

Steam pipes tested and minor repairs effected.


IT IS SUBMITTED that this vessel is eligible for the record BS 6.46, subject to the donkey boiler not being used until surveyed.

Examined 6.46.

Expunge DB pressure with thin red line.

Note in S.R.L:

Steam pipes tested 4.46.



24.8.46



© 2020

Lloyd's Register
Foundation

007958-007966-0085