

Port of

S.S. Corcyra. Engine repairs continued.
 Tested by hydraulic pressure the H.P. cylinder to 300 lbs I.P. cylinder 100 lbs
 + L.P. cylinder to 60 lbs with satisfactory results. Main steam pipe
 annealed + tested by hydraulic pressure to 400 lbs found light and
 sound. Other minor repairs effected.
 The Engines + boiler examined whilst being erected on the vessel,
 + examined under steam + the safety valves adjusted to
 200 lbs.

A.E. Farmer

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

Grounding damage
 Machinery removed from several
 beams, overhauled + afterwards
 fitted on board.

It is submitted that
 this vessel is eligible to
 remain as CLASSED.

S 2.17

[Signature]
 2.3.17