

TO COMPLETE THE SURVEY:-

All the rules requirements, except stated above to be done.

NOTE:- S.S.No.2 advanced, Owners state that this will be completed within 12 months.

ALTERATION:-

Wireless secondary battery room now newly fitted on boat deck, port side adjacent to wireless motor room (5 ft x 6 ft x 6 ft 6 ins.). Tonnage alteration will be measured by the Government Surveyor and will be reported when being decided.

REPAIRS DUE TO WEAR AND TEAR:-

About 500 corroded bottom rivets on keel plate in way of No.1 double bottom tank renewed.

1 main engine holding down bolt in way of No.5 double bottom tank renewed.

. All connecting rivets of main channel frame to margin bracket in starboard deep tank found slacked and now renewed.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.