

Rpt. S.

No. 449

(Received at London Office)

No. 117410. A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19...

58399 on the Wood, Iron or Steel s/s ESSO BAYWAY

TONNAGE :-  
GROSS 7699  
UNDER DK. 6943  
NET 4654

Built at Kearney 3g. By whom Federal S.B. DD Coy When 1937 - 11.

Owners Standard Oil Co (N.Y.) Owners' Address

Managers Port belonging to Wilmington Del.

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell DBor DBa feet; uE & B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 5078 Port Gal

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)  
CHARACTER: 100 A1 LMC 1.47  
1.49 BS 1.49  
SS N.Y.K. N°2-45 S.S. 9.47 (CL)N  
Carrying Petroleum in bulk.  
Fitted for oil fuel 11.37 F.P. above 150° F.  
Pl. also welded.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fairred or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" " In way of sidelights	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stimson	Cables (State if now ranged)
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Keelsons		" " at other places	" Rule length size
Stringers		Stringers, Clamps & Shelves	Chain Locker
Inner Bottom Plating		Salting	Hawsers & Warps
Have the Tanks been examined internally?		State if examined.	Standing and Running Rigging
Have the Tanks been tested?			Sails

General Observations, Opinion as to Class, Recommendation, &c. :-  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £ : : Fees applied for, 19...  
Special Damage or Repair Fee (if any) (per Sec. 29) £ : : Received by me, 19...  
Travelling Expenses (if chargeable) £ : :  
Second Surveyor's Fee (if any) £ : :  
Committee's Minute FRI. 22 JUL 1943 L. (Loree)  
Character Assigned Withdraw class & insert (...)

© 2021  
Surveyor to Lloyd's Register of Shipping.  
General Committee  
Thursday 19 September 1943  
Classing Committee  
Decision confirmed P.B.  
Lloyd's Register  
Foundation  
008028 - 008039 - 0197