



s.s. "BRAVORE"

It is submitted the Owners be informed that before duplicates of the certificates of chain cables and anchors now on board can be issued, the chain cables and anchors will require to be ranged and the marks thereon ascertained.

As the Cardiff Surveyors stated on the 3rd instant that the vessel was then in dry dock at their port particulars of the anchors and chain cables originally supplied to the vessel, and also of the anchor supplied while she was under survey in London in July 1920 (Report No. 83344), should be forwarded to them for their guidance when examining the anchors and cables, if this is done at their port.

 5.12.24 

also
on board
class.



© 2021

Lloyd's Register
Foundation

008087-008095-0198