

1 - DEC 1924

Received from Chief Surveyors

veyors

ME

Stl. Sc. Sr. "BRAVORE"

Report

Bry. No. 19383

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/22.)

No.2

When due

2,24

Indented plates. *As due 5.24.*

It is submitted the Owners' representatives be informed at two shell plates, F.4 and G.3, on the port side forward were reported by the Sunderland Surveyors in April 1923 to be indented and several other plates slightly indented, and it was recommended at these plates be dealt with at the Owners' convenience, but no further details are available in this Office, and the writers should confer with the local Surveyors as to the work which will require be carried out at the special survey.

to Mr Lr 1/12/24
also
Mr. Castle
via Lws (com)

Stk
7/12.24

[Signature]

[Signature]

[Signature]

28.11.24.



© 2021

Lloyd's Register
Foundation

008087-008095-0204