

Subject to ^{Permanent} repairs being carried out to indented bottom plating at the first convenient opportunity.

1 SEP 1931

Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____
NAME *M. T. Sc.* "EMBANEET" Rpt. *Ham* No. *20052*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.

Survey _____

The *Hamburg* Surveyors report this vessel placed in dock, bottom cleaned and coated and ~~minor repairs effected.~~
The indented plating referred to above has not been dealt with.
It is submitted the vessel appears worthy to remain as *Subject as above*
assessed with record of survey *7.31* as recommended.

1.00 A.1
7.31 Ham } *Subject re*
carrying Petroleum in bulk.

At
1.9.31



© 2020
Lloyd's Register
Foundation

008122-008128-0176