

DISCLOSED

DISCLOSED

(Received at London Office)

Lon No. 128874 A

SECTION

REPORT OF SURVEY FOR REPAIRS, &c.

No. 600

Date of survey Report 19... When handed in at Local Office 19... Port of

No. in Reg. Book Survey held at Date, First Survey Last Survey

28956 on the Wood, Iron or Steel S.S. TAAROA

TONNAGE: Built at AUCKLAND N.Z. By whom MASON BROS. ENG. CO. When 1943

GROSS 252 Owners NEW ZEALAND FISHERIES LTD. Owners' Address

UNDER DK 221 Managers Managers' Address

NET 88 Managers Managers' Address

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor DBa feet; uE&B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 3279. Port Ddu.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
Frames	Windlass
Reverse Frames	Have pumps been examined and found efficient?
Longitudinals	Have Sluice Valves been examined and found efficient?
Transverses	Have Watertight Doors been examined and found efficient?
Floors	Have Ventilators and their Coamings been examined and found efficient?
Keelsons	Air and Sounding Pipes
Stringers	Doubling Plates under Sounding Pipes
Inner Bottom Plating	
Have the Tanks been examined internally?	
Have the Tanks been tested?	
Engine Room Skylights	Copper, or Y.M.
Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Oil Bunkers	When fitted, Month Year
Scuppers	Boats
Cargo Hatchways	Masts, Yards, &c.
Hatches	Condition, how ascertained
Planking	(State if wedges removed.)
Caulking	Equipment letter
Treenails	Anchors, No. of
Breasthooks & Stemson	Cables (State if now ranged)
Transoms, Pointers & Crutches	length mean diamr.
Timbers of Frame at openings	(on board.)
Stringers, Clamps & Shelves	Rule length size
Salting	Chain Locker
(State if examined)	Hawsers & Warps
	Standing and Running Rigging
	Sails

General Observations, Opinion as to Class, Recommendation, &c. :

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

TUESDAY 4 MAY 1954

GENERAL COMMITTEE

Thursday 20th May 1954

Classing Committee's decision confirmed

Lloyd's Register Foundation

008146-008157-0085

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

MADE AND PRINTED IN ENGLAND. (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

In Certificate required? If so, to be sent to