

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 24.1.1952 When handed in at Local Office 24.1.1952 Port of Rio de Janeiro
No. in Survey held at Rio de Janeiro Date, First Survey 10.10.51 Last Survey 23.1.1952
Reg. Book. on the Wood Iron or Steel Aux. T.W.Sc. m.v. "TANGARA" (No. of Visits nine)

ONNAGE: Built at Port Glasgow By whom Russell & Co. When 1902 MONTH 1
3811 Owners Murray, Simonsen & Co. Ltd. Owners' Address
R DK 3551 Managers - Port belonging to Rio de Janeiro
3007

red Afloat or in Dry Dock? dry Name of Dock Viana Destined Voyage
Bor DBa feet; uE & B. feet; f feet
Capacity tons. FPT tons; APT tons; MT feet tons.

Daily alterations in the existing records of tanks should be inserted.

All alterations in the existing records should be underlined.

Report, No. 49504 Port Louv

Surveys, when held, must be reported in detail and serially in the terms of the Rules and Items remaining to complete
veys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations
sequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to
uses; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
ment of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.
so the dates and initials of any letters respecting this case. Classn. (S) 10.10.51

ge cases where the Surveyor has not made a special damage report he is required to state whether he
ered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

EXAMINATION AS PER RULE, FOR proposed reclassing.

el examined afloat and in drydock.

ined generally, decks, hatches and hatchways, bottom and rudder, hold spaces so far as
ticable, machinery spaces, fore peak tank internally and the shell and decks drilled as
attached list of drillings.

As a result of this preliminary examination, which showed that extensive shell and
plate renewals would be necessary the owners have now advised that they do not intend to
eed further with the proposed reclassing of the vessel.

emova of the deck wood sheathing the decks were found extensively holed amidships.

py of the preliminary findings issued to the owners on a Report 10 is attached herewith.

OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
ewed ...								
oved and Fair or Repaired								
ed or Repaired in place ...								

CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or V.M.
Fastenings	Ceiling	Coal Bunkers, Openings, Covers, &c.	State if on Pel.
ating	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
in way of lights	Rudder	Souppets	Boats
ames	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
als	Windlass	Hatches	Condition, how ascertained
s	Have pumps been examined and found effi- cient?	Planking	(State if wood removed)
	Have Sluice Valves been examined and found efficient?	Gaulking	Equipment (etc.)
	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. &c.
om Plating	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Strops	Cables (State if now raised)
Tanks been examined internally?	Alr and Sounding Pipes	Transoms, Painters & Crutches	length mean diamr.
Tanks been tested?	Doubling Plates under Sounding Pipes	Timbers of Frames at openings	(on board)
		" " at other places	Rule length size
		Stringers, Clamps & Shelves	Chalp Locker
		Salting	Hawsers & Warps
		State if examined.	Standing and Running Riggings
			Sails

ral Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
vey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This report is written for the information of the committee.

Survey Fee (per Section 29) 6.000,00

Special Damage or Repair Fee (if any) :

Travelling Expenses (if chargeable) 1.200,00

Second Surveyor's Fee (if any) Rigging 1.200,00

Committee's Minute

Character Assigned

Fees applied for,

23.1.1952

Received by

19

TUES. 11 MAR 1952

Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation