

Rpt. 8. No. 461. (Received at London Office) No. 117499A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 18544 Survey held at on the ~~Wood, Iron~~ Steel "MEADOW" (ex "EMPIRE MEADOW") Date, First Survey Last Survey 19... (No. of Visits...)

TONNAGE: GROSS 242 UNDER DK 229 NET... Built at Gainsborough By whom J. S. Watson (Gainsborough) Ltd When 1942 8 Owners J. Cooper Owners' Address Managers Port belonging to Belfast

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Cell/Dor/Dba feet; uE&B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements) CHARACTER: * for Special Survey Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any). +100A1 + LMC 946 For towing services BS. 1048. 3.49. TS 11.48 (O.G.) SS Bel. 946.

Last Report, No. 14738 Port Bel. N.B.—All alterations in the existing records of tanks should be inserted. N.B.—All alterations in the existing records should be underlined.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified ft ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " in way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes
Stringers	Engine Room Skylights
Inner Bottom Plating	Coal Bunkers, Openings, Covers, &c.
Have the Tanks been examined internally?	Oil Bunkers
Have the Tanks been tested?	Scuppers
	Cargo Hatchways
	Hatches
	Planking
	Caulking
	Treenails
	Breasthooks & Stemson
	Transoms, Pointers & Crutches
	Timbers of Frame at openings
	" " at other places
	Stringers, Clamps & Shelves
	Salting
	State if examined.
	Copper, or Y.M. (State if on Felt.)
	When fitted, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed.)
	Equipment letter
	Anchor, No. of
	Cables (State if now ranged)
	" length mean diam. (on board.)
	" Rule length size
	Chain Locker
	Hawsers & Warps
	Standing and Running Rigging
	Sails

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee (per Section 29) £... Special Damage or Repair Fee (if any) (per Sec. 29) £... Travelling Expenses (if chargeable) £... Second Surveyor's Fee (if any) £... Fees applied for, 19... Received by me, 19...

Committee's Minute. 9 DEC 1949. Character Assigned. write Bel. Special General Committee Thursday, 15th December 1949. Glassing Committee duly confirmed. fbb

18544

If so, is the Report sent now, or when will it be sent?

008258-008267-0061

