

Twin Screw Motorship "THORHILD"

The posting of the record in col. 7* of
"shafts seen 4,44" was an error, and is regretted.
The screwshaft cones were examined at that time
but the shafts were not drawn.

Both shafts were drawn and examined in 9,44.
This record was duly posted and appeared in Supp. No.10
to the 1944-45 R.B. (dated 18.12.44).

Huly

11th July, 1952.



© 2021

Lloyd's Register
Foundation

008258-008267-0159