

DISCLOSED SECTION.

SECTION

Rpt. 8.

No. 437

(Received at London Office)

No. 117546A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 02004 Survey held at on the Wood, Iron or Steel ss "ASTRA" Date, First Survey Last Survey

By whom *Araker & Stans Hendrik Ltd* When 1907 - 3

Owners "Astora" Co Argentina de Petroleos Owners' Address Soc Anon. Port belonging to Buenos Aires

Managers

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor D Ba feet; uE & B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 21545 Port BAW

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER	Machinery and Boiler Surveys
* for Special Survey	(Including date of N.B., if any)
Date of last Survey and of Periodical Surveys	
100 A1	LMC 7.45
10 47	RS 9.48
SS B.Hs 3 rd No 3 - 7.45	TS 9.47
Converted to Tanker '21	
Carrying Petroleum in bulk	
Fitted for oil fuel 5.19 F.P. above 150°F	
Society's Freeboard (if assigned) as painted on Ship and now verified	ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :—
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Celling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Planking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Stamings	Rudder	Scuppers	Boats
Rams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" In way of sidelights	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Inverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Stems	Doubling Plates under Sounding Pipes	Timbers of Framo at openings	(on board.)
Side Frames		" " at other places	" Rule length size
Inner Bottom		Stringers, Clamps & Shelves	Chain Locker
Decks		Salting	Hawsers & Warps
Planking		State if examined.	Standing and Running Rigging
Stamings			Sails

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee	£	:	:	Fees applied for,
Survey Fee (per Section 29)				19
Damage or Repair Fee (if any) (per Sec. 29)				
Printing Expenses (if chargeable)				19
Surveyor's Fee (if any)				

Committee's Minute FEB 10 FEB 1950

Character Assigned

Surveyor to Lloyd's Register of Shipping
 Special General Committee
 Tuesday 23rd March 1950
 Classify Committee's decision
 Lloyd's Register Foundation
 008288-008295-0222

ASTRA
 ARGENTINA
 SOCIEDAD ANON
 AVENIDA ALLEN
 BUENOS AIRES

CLASIFICACION

Muy se
 inspe
 de un
 menta
 sific

30

Is certificate required? If so, to be sent to