

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

These boilers have been built under Special Survey.
 The materials and workmanship are good.
 They have been despatched to Middleborough for fitting on board.
 These boilers have now been securely fitted on board, mounted and casing gear fitted.

Thomas Miller.

Certificate (if required) to be sent to
 Committee's Minute.
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	:	:	When applied for,
1/3 Special £ 14 -	:	:	28/9/20
Donkey Boiler Fee £	:	:	advised from La. R.D. Philston
Travelling Expenses (if any) £	:	:	13/10/20

R.D. Philston
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping

Thomas Miller

Committee's Minute

TUE. JAN. 25 1921

Assigned



© 2020

Lloyd's Register
 Foundation

Rpt
 No.
 Reg.
 Mast
 Engin
 Boile
 Regis
 TU
 Lette
 Boile
 To. o
 Safety
 re t
 mall
 later
 descr
 ap
 ules
 oller
 descr
 later
 Top
 malle
 pitch
 rea
 ower
 pitch
 water
 irder
 Vork
 separ
 oles
 f stij
 Vork
 VEE
 lade
 sted
 No. of
 ater
 treng
 ap o
 radiu
 Thicker
 lates
 Thicker
 Dat
 of Su
 whi
 build