

Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under

008472-008480-0147

The class is subject to the fit of the starboard LP
Kpin in after web being specially examined by R.49. 5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME MANUEL CALVO

REPORT

BBo

No. 10567

If the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE & WEAR AND TEAR.

The Bilbao Surveyor reports some further Boiler survey work, although this survey was completed at Barcelona in July last.

It is submitted the vessel is eligible to remain as classed, with

as recommended, subject as above.



© 2020

Lloyd's Register
Foundation

15.11.49

Observations, Opinion, and Recommendation:— The machinery of this vessel is

to be made in the records of the vessel's machinery in the Register Book, consequent upon this sur