

(Received at London Office

16

Is a Certificate required? If so, to be sent to—

"SPRINGBANK".

Screwshaft 15.1/4" dia. Length of Sternbush 61".

Bronze { Thickness 25/32" Shaft { Dia. of bolts 3.3/8".
Liner { Thickness between bushes .72". Coupling { Thickness of flange 3.3/8".

Spare screw shaft placed onboard and marked as follows:-

1928
LLOYD'S 1495
W.B. W.B.
W.A.L.
26.9.47.

Forging Report attached hereto.

B.S.:-

Both main boilers examined in their entirety together with mountings and found or placed in satisfactory condition. (Superheaters specially examined).
Safety valves adjusted under steam to 250 lbs/sq.in.
It is submitted that the boilers be accepted for B.S. (Classification).
First Entry Report attached.

Interim Certificate issued - copy attached hereto.

L. Smith



© 2020

Lloyd's Register
Foundation