

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME "EL BUARO" REPORT -- No. --

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey..... When due.....

From the Lloyd's Agents' report of survey held at Callao August/October, 1953, it was concluded that there was a stream anchor on board.

In reply to an enquiry the Lloyd's Agents' Surveyor at Lima in a letter dated 26.4.54 advises that there is no stream anchor on board at present.

When this ship was under Special Survey at Balboa March/May, 1951, a stream anchor was reported to be on board.

IT IS SUBMITTED this ship is worthy to be continued as classed, subject to a stream anchor being supplied at the earliest opportunity.

As Now. Subject.

IT IS ALSO SUBMITTED that the Owners be informed of the foregoing deficiency and be requested to advise when and where a stream anchor as required by the Rules will be placed on board.

4  
5  
54  
LH



© 2021

Lloyd's Register  
Foundation

008550-008558-0292