

24 JAN 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME TJISAROE Rpt. Sba No. 4456

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The class is subject to indented shell plate A.12 from aft being faired and No. 1 D.B. tank (p.s) being examined internally at the first opportunity (and to 15 fathoms of chain cable being supplied).

The 2nd S.S. No. 1 became due 10.41.

The SOURABAYA Surveyor reports (9.41) the vessel examined in dry dock after grounding and the bottom coated. No. 1 D.B. tank (p.s) has now been examined internally and no damage or leakage found.

The doubling on shell plate as above found in order and in the Surveyor's opinion this may be considered a permanent repair.

It is submitted the vessel appears worthy to remain as classed with record of survey 9.41 (subject to 15 fathoms of chain cable being supplied) but without other condition.

100A1)	
With fbd)	Subject etc.
9.41 Sba)	
Carrying molasses)	Without etc.
in deep tank.)	



© 2021

21.1.42

Lloyd's Register
Foundation