

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 161 19...

60288 on the Wood, Iron or Steel S.S. "Yesso" By whom J. J. Abdela Mitchell, Esq. When 1918

TONNAGE:- Built at Queensferry Owners Diamond S.F. Co. Ltd. Managers

GROSS 206 UNDER DK. 202 NET 94 Port belonging to Gimsby

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. } 100 Ft. Steam Trawler. 3.24. S.S. hull No. 3-9.20.

Last Report, No. 13866 Port Gms

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	State if Tanks have been examined inside
Caulking of Decks	State if Tanks now tested
Coamings	Bulkheads
Beams & Fastenings	Ceiling
Outside Plating	Cement or Asphalt (State which.)
Breasthooks	Rudder
Transoms	Steering gear and its connections
Frames	Windlass
Reverse Frames	Have Pumps now been examined and found efficient?
Longitudinals	Have Sluice Valves now been examined and found efficient?
Transverses	Have Watertight Doors now been examined and found efficient?
Floors	Have Ventilators and their Coamings been examined and found efficient?
Keelsons	
Stringers	
Inner Bottom Plating	
	Dblng. Plates under Sounding Pipes
	Engine Room Skylights
	Coal Bunkers, Open'gs, Lids, &c.
	Scuppers
	Cargo Hatchways
	Hatches
	Planking of Wood Vessels
	Caulking ditto
	Treemails ditto
	Breasthooks & Stemson ditto
	Transoms, Pointers, & Crutches ditto
	Timbers of Frame at openings ditto
	Ditto ditto at other places ditto
	Stringers, Clamps & Shelves ditto
	Salting ditto (State if examined.)
	Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed)
	Sails
	Equipment letter
	Anchors, No. of
	Cables (State if now ranged)
	length size (on board)
	Rule length size
	Hawser & Warps
	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND15, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute FRI. 13 FEB 1925 Surveyor to Lloyd's Register of Shipping.

Character Assigned withdraw class + insert (. . .) Classing for me this decision confirmed

Has a survey also been held on the Machinery of the Ship? If so, is the Report sent here, or when will it be sent?

Is Certificate required? If so, to be sent to

10m. 10.24.—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)