

008641-008677-0077

Surveyors

Received from Chief Surveyors.

ME *M. S. S. Tocantins*

Report *N. Yk.* No. 18113

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

No. */* SURVEY PARTLY HELD.


6.19

When proposed to be completed

held, &c.,

To complete the Survey: All rule requirements
Excepting Examination of bottom in drydock and of
steering gear & connections.
Fire damage to be permanently repaired.

PLATING to be DRILLED when vessel
is 24 years old, or at next special
survey thereafter.



© 2021

Lloyd's Register
Foundation