

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor 19 FEB 1957

SHIP'S NAME

"NORD"

REPORT

Cpn.

No. 16163

Docking. Screwshaft seen after damage through cause not stated, and propeller faired. Some minor surface corrosion noted on some of the main engine crankpins and journals, and the Surveyor recommends that all main engine crankpins and journals be specially examined and dealt with as necessary before the end of 5,57.

C.S. Advanced.

IT IS SUBMITTED that this vessel is eligible for the record TS. 1,57, subject as recommended.

ENDORSEMENT (B) MACHY.

15.2.57.

Lloyd's Register  
Foundation

008656-008668-0077