

Received from Chief Ship Surveyor

12 OCT 1959

P/S NAME "NORTHERN EAGLE"
Ex "OILFIELD"

REPORT

Cff. No. 60934

standing Conditions of Class:

SUBJECT to permanent repairs to set up keel plate No. 3 and adjoining A.4 (p & s) and indented shell plates F.8 & G.6 (p.s.), G.2 (s.s.), at next Special Survey, also to shell plates G.7, 8, 11, 12 & 13, H.6, 7, 8, 11, 12 & 13, J.6, 7, 8 & 12 (p.s.) and G.7, H.7, 8, 11 & 12, J.8, 11 & 12 (s.s.) being specially examined and dealt with as necessary by next drydocking,

L. Appendix. (As before ~~or None~~)

ure of Present Survey: (~~Amended~~ and in dry dock)

Drydocking: Deferred repairs.

ommendation:

SUBMITTED record of 'DS 9,59' be assigned as recommended, SUBJECT to indented shell plates F.8 & 9, G.6, 12, 13 & 14, H.8, 13 & 14, J.7 & 8 (p.s. from fwd), G.2, 7 & 8, H.8, J.12 (s.s. from fwd) and keel plates Nos. 3 & 4 from fwd, also starboard bilge keel being specially examined and dealt with as necessary next drydocking, but without other conditions.

DS 9,59 Subject, Amended,
Without.

IN S.R.L. APPENDIX.

Set up keel strake.

Indents in side shell plating (p & s).

OFFICE NOTE

Docking brackets fitted - Nwc. 12,53,
with minor corrugations left unfaired.

FREEBOARD SURVEYORS ~~TO~~ NOTE

Blk (new)



© 2021

Lloyd's Register
Foundation

008656-008668-0114

13-10-59