

Rpt. 8.

DISCLOSED SECTION No. 1152254 London No. 1152254

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19...

No. in Reg. Book 6952 Survey held at on the Wood, Iron Steel SS "EMPERE LOLA" Date, First Survey Last Survey 310

TONNAGE: GROSS 295, UNDER DK. 262, NET - Built at Greenock By whom G. Brown & Co. (Marine) Ltd. Owners The Admiralty Owners' Address - Port belonging to Greenock

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor DBa feet; uE & B... feet; f... feet total capacity tons. FPT tons; APT tons; MT... feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Last Report, No. 3138 Port Gib. Fitted for oil fuel 4.46 F.P. above 150°F

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examination, and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Plating of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Stowings	Cement or Asphalt	Oil Bunkers	Boats
Rivets & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Side Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" in way of sidelights	Windlass	Hatches	Equipment letter
Stowage Frames	Have pumps been examined and found efficient?	Planking	Anchor, No. of
Longitudinals	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Transverses	Have Watertight Doors been examined and found efficient?	Treenails	" length (on board.) mean diam.
Stowage	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Inner Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Have the Tanks been examined internally?	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Have the Tanks been tested?		" " at other places	Standing and Running Rigging
		Stringers, Clamps & Shelves	Sails
		Salting	

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute... Character Assigned... Delise classed all particulars on reprint... Surveyor to Lloyd's Register of Shipping... General Committee Thursday 11th September 1947... Lloyd's Register Foundation

10th ed. 1944. Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

Is Certificate required? If so, to be sent to

008669-008678-0286