

Gls. Rep. 27422.

It is concluded that the thickness of the front bottom plate of the auxiliary boiler is 1" as shown on the plan, & not $\frac{29}{32}$ " as given in the report. It is submitted that the Glasgow Surveyors be requested to state if this is so.

APRIL

17.2.09

Lr: - 18/2/09

008711 - 008719 - 0130

© 2021

Lloyd's Register
Foundation