


11 JAN 1940

Trawler "DANE"

*See letter  
15.1.40*

The Surveyors should be informed that it is concluded that the bottom and rudder have been examined and that the bottom has been coated. ✓

They should also be informed that in accordance with their letter of the 29.11.39 in addition to the items mentioned in their report the tunnel space, ventilators, sounding pipes and mast wedges require to be examined, further that in addition to the repairs recommended by them there remains to be dealt with permanent repairs to the E. & B. Casings as required by the Liv. Rpt. 113226, and they should state if this is so. ✓



© 2020

Lloyd's Register  
Foundation

008728-008773-0161