

TEST REPORT

Name of Vessel : HIKOSAN MARU

Messrs. 4800 HP Propulsion Turbine

Repair work of HP 1st Gear

(Date. Nov. 30 - Dec. 2 1960)

Subject.

ISHIKAWAJIMA-HARIMA HEAVY INDUSTRIES CO., LTD.

TOKYO, JAPAN



© 2021

Lloyd's Register
Foundation

H.P. 1st Wheel aft Helix before Repair



© 2021

Lloyd's Register
Foundation

00203/19

H.P. 1st Wheel aft Helix before Repair

S

0026 2/19




© 2021

Lloyd's Register
Foundation

0020 3/19

H.P. 1st Wheel Aft Helix after Repaired (Grinding)



H.P. 1st Wheel Aft Helix after Repaired (Grinding)



© 2021
Lloyd's Register
Foundation

0026 6/19

H.P. 1st Wheel Aft Helix after Repaired (Grinding)

18

0026 4/19

H.P. 1st Wheel Aft Helix after Repaired (Grinding)

19



© 2021

0026 5/14

Lloyd's Register
Foundation

0026 6/19

H.P. 1st Wheel aft Helix Dyecheck Inspection after Repaired.



© 2021

Lloyd's Register
Foundation

0026 8/19

H.P. 1st Wheel aft Helix Dyecheck Inspection after Repaired

✓

0026 7/14



© 2021

Lloyd's Register
Foundation

0026 8/14

H.P. 1st Wheel aft Helix before Repair



© 2021

Lloyd's Register
Foundation

002610/14

H.P. 1st Wheel aft Helix before Repair

3

0026 9/14




© 2021

Lloyd's Register
Foundation

0026 10/14

H.P. 1st Wheel Aft Helix after Repaired (Grinding)



H.P. 1st Wheel Aft Helix after Repaired (Grinding)



© 2021
Lloyd's Register
Foundation

0026 13/19


H.P. 1st Wheel Aft Helix after Repaired (Grinding)

15

0026 11/19

H.P. 1st Wheel Aft Helix after Repaired (Grinding)

10



© 2021

Lloyd's Register
Foundation

0026 12/19
0026 13/19

H.P. 1st Wheel Fore Helix Dyecheck Inspection after Repaired



H.P. 1st Wheel aft Helix Dyecheck Inspection after Repaired



© 2021

Lloyd's Register
Foundation

0626 16/19


H.P. 1st Wheel Fore Helix Dyecheck Inspection after Repaired

28

0026 14/19

H.P. 1st Wheel aft Helix Dyecheck Inspection after Repaired

29



© 2021

Lloyd's Register
Foundation

0026

0026

15/19
16/19

HP 4800馬力 HIKOSAN MARU 彦山丸


1-Dec-1960 昭 35.12.1

at yokohama port.
(於横浜セーラー-105)

HP 1st WHEEL
高圧一段 木斗-14


箱側
FORE

AFTER
腹側



HP 1st PINION
高圧一段 $\angle = \alpha$

TEETH CONTACT
歯当り



LP 1st WHEEL (AFORE HELIX)
低圧一段 木斗-14 (箱側)

箱
FORE



© 2021

Lloyd's Register
Foundation




御証印

検査成績表

検第

号

配布先	注文主	工事番号	図面番号	発行年月日
注文主	船名(番)	材料	試験番号	検査年月日
船主	納入先	数量	機番	検査場所
	工名		機号	
	部名		検査事項	

(手入前)
BEFORE REPAIR艀
AFT艀
FOREPart A
A 部Part B
B 部

第三工場検査部

課長 田中 12.8


課長 35.12.9

係長 3.12.8


計測者 山本

号


(手入後)
AFTER REPAIR



A 部



B 部

[illegible]