

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME "INTAN"

REPORT

Gro	911
Ams	18925
Ams	No. 18869
Ams	19127

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 4SCSA

8 cylinders 10 $\frac{5}{8}$ " - 19.11/16"

New MN 100

~~If-Boilers-fitted-with-forced-draught~~

Tail Shaft. If fitted with a continuous liner No

If fitted with an outside gland of approved type Yes

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 8.1.53. for a service speed of 325 RPM.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *LMC 1,54

16.2.54.



© 2021

Lloyd's Register
Foundation

008804 - 008811 - 0028