

(Received at London Office 30 AUG 1929)

008804. 008811 - 0161

...

cracks in both bedplates in way of gaps for main bearings to be welded or otherwise repaired, all cylinders to be cleaned and water jackets cleared, cylinder heads to be renewed as necessary, rivetting of seat for after generator to be overhauled, air pressure tanks, etc., to be cleaned out.

"ALJUS" V M

130P6

It should be mentioned that when the vessel came into this port last time she was towed in by two tugs, owing to a piston in the starboard engine having fractured and to the general condition of the machinery.

H. R. Hebbleland.

11 3M1+ 256 1A001+ (M) 5M1
p 0 25-126 22
256 9
256 12

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

the vessel was towed into the port last time she was towed in by two tugs, owing to a piston in the starboard engine having fractured and to the general condition of the machinery. It should be mentioned that when the vessel came into this port last time she was towed in by two tugs, owing to a piston in the starboard engine having fractured and to the general condition of the machinery.

attested at the office of the Surveyors

H. R. Hebbleland

25 11 1900 00.00.00



© 2021

Lloyd's Register Foundation