

the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to and besides being detailed.

tender serv
10, 13
ker tank

DISCLOSED
SECTION
No. 395

S.S. "FRESHWELL".

This vessel was built in 1943 for the Admiralty and classed in the Ghost Book 100 A.L. for Admiralty tender services.

A letter has now been received from the Admiralty stating that this vessel is now sailing under the Blue Ensign.

IT IS SUBMITTED the class of this vessel be deleted from the Ghost Book.

J. G. L.
28.4.48.



© 2021

Lloyd's Register
Foundation

008812-008822-0050