

4m, 9, 41.

19 APR 1945

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "FRESHBURN" REPORT Drt. No. 7666

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The DARTMOUTH Surveyor reports this vessel placed in dry dock, bottom coated and due to damage through frequent berthings in a foul berth, temporary repairs effected to fractured No.3 shell plate in 3rd below sheer (s.s.) and to indented shell plating in 1st, 2nd and 3rd strakes below sheer (p & s). The Surveyor recommends permanent repairs at the Owners' convenience.

Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with record of docking survey 3.45 subject as now recommended.

3.45 Drt. subject.

18.4.45.



© 2021

Lloyd's Register  
Foundation

008812 - 008822 - 0313

Stringers.....

Have Ventilators and their Coamings been

examined and found satisfactory

" " at other places

Chain Locker