

Do. of excess of Hatchways
Do. above Crown of
Engine Room ..)

12.90

Girth of Half Midship Frame (as per Rule) 14.12

40.30

By whom built

J. B. M.
East-End

(2m, 11.5.)

1.

Sent to Chief Surveyors 23. 1. 06

Received from Chief Surveyors

VESSEL'S NAME *Sta. S. S. "Sea Nymph"*

Report *Link*. No. 14545

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

± 100 A1 ("Steel")

1 DR (See) *Will Link.*

N. B = FPT 236 APT 15

BK 7" 38H *Am. Lloyd's A&CP* Q63' B9' F18' *Moley Aft.*

C. H. J.
23/1/06



© 2021

Lloyd's Register
Foundation

008823 - 008830 - 00246

PILLARS, In 'tween Decks, Size and Spacing

Hold

42	42	42	42
2 1/2	DIA	42	2 1/2
2 1/2	DIA	42	2 1/2

THE PLATES

Deck, Material and thickness

1P

Forecastle Deck Stringer Plate, brdth & thcknss

5 x 2 1/2
25