

Lloyd's Register
Foundation

afterwards fitted in place and left in good working condition.

WEAR AND TEAR REPAIRS:-

Both tube plates of main condenser renewed. Ferrules renewed as required. On completion of repairs the condenser tested by a head of water with satisfactory results.

Damage through firing a lighter.
N.B.-If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damaged as to spread the ink, or to cause it to show through to the other side.
Screw shaft examined propeller renewed
B.S. due 6.27. Told machinery also examined
Condenser tube plates renewed & small
repairs effected.

It is submitted that
this vessel is eligible for
THE RECORD. + L.M.C. 7.27.

88.7.27

[Signature]
16/9/27

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation