

Rpt.

(Received at London Office)

-4 SEP 1941

DISCLOSED

NAV No.

12645

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 24th June 41 When handed in at Local Office 24th June 41 Port of SHIMONOSEKI.

No. in
Reg. Book.

Survey held at SHIMONOSEKI

Date, First Survey 29th May Last Survey 20th June 1941.

74966 on the ~~Wakayama~~ Steel Single Screw Steamer "GLASGOW MARU".

TONNAGE:-

Built at

Kobe

By whom

Kawasaki Kiyd Co. Ltd.

When 1919

MONTH.

4

GROSS 5831

UNDER DK 5586

NET 4227

Owners Kokusai Kisen K.K.

Owners' Address

(if not already recorded in Appendix to Register Book)

Managers

Port belonging to Kobe

veyed Afloat or in Dry Dock? Both Name of Dock Mitsubishi Hikoshima Dock Destined Voyage

DBorDBa feet; uE&B feet; f feet
l capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

V.B.—All alterations in the existing records should be underlined.

st Report, No. 2599 Port Smk.

odical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to
omplete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and
tent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated)
ould be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be
mmarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars
ould be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters
pecting this case.

amage cases where the Surveyor has not made a special damage report he is required to state whether he
ffered his services for this purpose and to whom and why they were declined Offered & Accepted

Society's Freeboard (if assigned) as
painted on Ship and now verified

ft. ins.

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR Condition Survey and Repairs of Damage (S.R.L), stated to have
n caused by vessel touching with lighters at Dungun.

further particulars see Smk. Damage reports, dated 30th July 1940 and 23rd June 1941.

Done:- Vessel placed in dry dock, bottom, stern frame & rudder cleaned, examined, found or now
placed in good condition and recoated.

Decks, hatchways, hatches and supports, ventilators & coamings, holds & tween deck spaces,
and general equipment generally examined and found or now placed in good condition.

Plating in way of ash shoot examined and found in good condition.

Windlass and steering gear examined and found or now placed in good condition.

L:- Permanent repairs to shell plating on port side aft now carried out as stated below, and
the restriction may be removed from the S.R.L.

P. T. O.

ARY OF DAMAGE REPAIRS:-

	Shell Plates.	Frames.	E. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed ...	1	/	/	/	/	/	/	1 plate part doubled.
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

ENT CONDITION OF THE

Good	Bulkheads	/	Engine Room Skylights	/	Copper, or Y.M. (State if on Felt.)	/
Good	Ceiling	/	Coal Bunkers, Openings, Covers, &c.	/	When fitted, Month	Year
Good	Cement or Asphalt	/	Oil Bunkers	/	Boats	Good
Good	Rudder	Good	Scuppers	/	Masts, Yards, &c.	"
Good	Steering gear and its connections	"	Cargo Hatchways	Good	Condition, how ascertained	From dk
Good	Windlass	"	Hatches	"	(State if wedges removed)	
Good	Have pumps been examined and found effi-	/	Planking	/	Equipment letter	/
Good	cient?	/	Caulking	/	Anchors, No. of	/
Good	Have Sluice Valves been examined and found effi-	/	Treenails	/	Cables (State if now ranged)	/
Good	cient?	/	Breasthooks & Stemson	/	" length	/
Good	Have Watertight Doors been examined and found	/	Transoms, Pointers & Crutches	/	(on board) / mean diamr.	/
Good	efficient?	/	Timbers of Frame at openings	/	" Rule length	size
Good	Have Ventilators and their Coamings been examined	/	" " at other places	/	Chain Locker	/
Good	and found efficient?	Yes	Stringers, Clamps & Shelves	/	Hawsers & Warps	Good
Good	Air and Sounding Pipes	/	Salting	/	Standing and Running Rigging	"
Good	Doubling Plates under Sounding Pipes	/	(State if examined.)	/	Sails	/

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel so far as now seen, is in good condition and eligible in my opinion to be continued
as classed with fresh record of survey, 6.-'41.

Survey Fee (per Section 20) £ 115:00

Fees applied for,
23. 6. 19. 41

Special Damage or Repair Fee (if any) £ 100:00

Received by me,
19

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI. 19 SEP 1941

Character Assigned

1000. Spl. Cond
Awn. Dr. w/ft
+ dmb. 6. 4. 1
Subnet

Lloyd's Register
Foundation

008863-008870-0043

Repairs due to wear & tear (SRL):-

Shell plates on port side aft.

No.4 plate in 3rd strake below sheerstrake- now part doubled.

No.3 plate in 4th strake below sheerstrake- now renewed.

On completion of repairs, repairs hose tested and found tight.

Repairs due to wear & tear:-

Nos.10 & 11 plates (from aft) in 3rd strake and No.9 plate (from aft) in 4th strake below upper deck sheerstrake on port side- part doubled.

No.2 plate (from forward) in D strake on starboard side- renewed.

3- 2nd deck plates in starboard side bunker- part renewed.

On completion of repairs, repairs hose tested as necessary and found tight.

Other repairs of minor nature effected.

T.K.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

While the
ted, it is to
ver to be h
in the Regis
uttees or an

20m.1139

e (per Sectio

4.

(per Section

expenses (in

Committee's

7

[illegible]

11