

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of *Genoa*

No. in Survey held at Date, First Survey Last Survey 19
Reg. Book. *on the Wood, Iron or Steel* "FORTUNSTELLA" (No. of Visits)

TONNAGE:-
GROSS *4864*
UNDER DK. *4239*
NET *2934*
Built at *Newcastle* By whom *Palmero's Co., Ltd* When *1912* MONTH *12*
Owners *Fratelli Rizzuto* Owners' Address
Managers Port belonging to *Genoa*

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Cell DBor DBa feet; uE&B feet; f feet }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.
Last Report, No. Port

CHARACTER. *+100A1*
Date of last Survey and of Periodical Surveys. *Shelter deck with freeboard 1,38*
Machinery and Boiler Surveys (including date of N.B., if any). *+LMC 11,34*
BS. 10,38
TS(CL) 1,38.
A.A. Ska No. 3.-1,34

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR
MAINTENANCE OF DECK
MAINTENANCE OF BULKHEADS
MAINTENANCE OF RIGGING

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchor, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails (State if examined.)
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £
Special Damage or Repair Fee (if any) (per Sec. 29) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £
Fees applied for,
Received by me,
19.....

Committee's Minute
Character Assigned *Deferred for*
Wife's Sn. Comp. 2d. No. 3
(Drilling approved subject)
FRI. 5 JAN 1940
Surveyor to Lloyd's Register of Shipping.
© 2020 Lloyd's Register Foundation

10m. 4.38.—Transfer Ink. (MADE AND PRINTED IN ENGLAND) Surveyors are requested not to write on or below the space for Committee's Minutes.

This Certificate required if so, to be sent to

