

25 AUG 1925

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *St. L. L. "SUNFLOWER"*Rpt. *Sub*No. *1866*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Sub:- *2 indented shell plates and one frame on starboard bow to be faired at the owners convenience.*

Survey

Damage through

*Grounding.**(Cis 1519)*

How repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							
Other items:-	<i>vessel placed in drydock, bottom cleaned & coated</i> <i>minor repairs effected</i>						

working has been done at this time to effect repairs to indented shell plates mentioned above

(See Endorsement dated 19.8.25)

It is submitted the vessel is worthy to remain as classed with record of Survey *8.25 Sub* as recommended. *subject as above*

100A.1.

8.25 Sub

Carrying petroleum in Bulk
Fitted for oil fuel etc

subject etc

© 2020
 Lloyd's Register
 Foundation

008993-009003-0406