

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water

L.C.T. No 3.


Buo. 2557
Nyx 31527
Blv. 526.

It is submitted that
this vessel is eligible for
THE RECORD + L.M.C. 6.30

Oil Engines 4 S.C.S.A 12cy. 11"-15" C-L

N.H.P. 142.

2 Oil Engines connected to Elec. Motor
2 Sc. Shaft.



© 2021 Lloyd's Register
Foundation

[Signature]
20/7/30.

004064-004007-083

Are all the Bilge Suction pipes in Holds and Tunnel well fitted with strum-boxes..... Are the