

23 OCT 1948

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

S NAME "INDIA" REPORT Lon. No. 117207

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

A NOTATION of "Examined 11.47" is assigned.

The class is subject to permanent repairs to wasted shell plate at end of ladder well in way of after F.W. tank at the next drydocking, to indented plating on port bow at the first convenient opportunity.

The LONDON Surveyors report 10.48, the vessel afloat and a PERIODICAL SPECIAL SURVEY commenced, and repairs effected to shell plating etc. (s.s.f), on account of collision damage.

TO COMPLETE S.S. - See Report.

120 fathoms of stream chain cable have been placed aboard at this time and verified.

It is submitted the vessel is eligible to remain as classed, subject as above.

As now. Subject.

S.S. Part Held.



Lloyd's Register
Foundation

009008-009014-0089

no further changed