

placed in good condition and recoated.

Subject to the top gudgeon on sternframe (EW. 3,40) being specially examined at the next dry docking

3m. 9.37.

11

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Fausang Rpt. Hkg No. 8778

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey Docking

The Hong Kong Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs to shell plating over laps where worn. 2 upper deck plates (SS) renewed and minor repairs effected.

Top gudgeon of sternframe EW 3,40 (as above) examined + found satisfactory

It is submitted the vessel appears worthy to remain as classed with record of survey 5,41 as recommended. Subject as above

100A1. }
5,41 Hkg. } Subject etc



© 2020

CoPM

29-7-41

Lloyd's Register Foundation

009008-009014-0175

remain as classed and to have record of survey 5-41. Top gudgeon on stern frame