

F.E.

Chief Ship Surveyor 23/1/12  
NAME At SS 'Daisy' Rpt. Abu No. 10747

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)


Reverse No. 35-50 Depth "d" 11-66  
Table No. 3 page 9 Description Single angle, as  
Longitudinal No. 4437 approved.  
Proportions  $\frac{\text{Length}}{\text{Depth}} = \underline{9.6}$

~~Deck~~ Sheerstrake .50 in lieu of .34 as required  
by the Rules.

This vessel appears to have been built in accordance with the  
and the approved plans, and it is submitted she is eligible to  
be classed + 100 A1 (Steel) as recommended.

+ 100 A1. (Steel)

BR 7 1/2 CBH 6mm. Lloyds at 60 F24



2021 RPH  
23/1/12

The Surveyor should be requested to forward  
the breaking test of the chain cables.

the Daisy. but same are being re-arranged to be